



Fuxin, Liaoning

Coaling/Depot  
Wulong Yard

Stabling point/Crew change  
Works

Power station  
Taiping

Gaode

Spoil tipping

Hai Zhou mine

Mine??

Power station  
Chengnan

Power station  
Cement works (disused)

Coal tipping  
Pingan mine

Electric Rly  
Level crossing

Tip

Wulong mine

New level crossing

Halt

Coal loading

Back entrance

Electric rly system

Sunjlawan mine tip

Main entrance

cableway

Stone tipping line

Wangying mine

3.58 km

© 2015 AutoNavi  
Image © 2015 DigitalGlobe  
Image © 2015 CNES / Astrium

Google earth